ALASKA DIVISION OF GEOLOGICAL & GEOPHYSICAL SURVEYS

PRELIMINARY INTERPRETIVE REPORT 2008-3a
Reger and others (2008)
SHEET 1 of 2
Explanatory text accompanies map

SURFICIAL-GEOLOGIC MAP, ALASKA HIGHWAY CORRIDOR, DELTA JUNCTION TO DOT LAKE, ALASKA

by
R.D. Reger[1], D.S.P. Stevens[2], and D.N. Solie[2]

Affiliations
[1] Reger's Geologic Consulting, Soldotna, Alaska
[2] Alaska Division of Geological & Geophysical Surveys



Topographic base map from:
Big Delta A-3 and A-4; Mount Hayes C-3, D-3, and D-4 quadrangles,
U.S. Geological Survey digital raster graphic images, 1997
Map projection: UTM zone 6
Datum: NAD 27

Air photo interpretation by:
R.D. Reger (2007)
GIS layers digitized by:
D.S.P. Stevens
Map unit patterns by:
A.G. Sturmann
Digital cartography by:
K.E. Obermiller
Surficial-geologic field work by:
R.D. Reger, D.S.P. Stevens and D.N. Solie (2006, 2007)
Active faults mapped by:
G.A. Carver (Carver and others, 2008)
Reviewed by:
R.A. Combellick



Maps Showing Location of Study Area

SCALE 1:63,360

CONTOUR INTERVAL 100 FEET
DATUM IS MEAN SEA LEVEL

APPROXIMATE MEAN DECLINATION, 2007

DESCRIPTION OF SURFICIAL-GEOLOGIC MAP UNITS

(All map units may not appear on this sheet)

The accompanying map shows the distribution of unconsolidated deposits and undifferentiated bedrock exposed at the surface in the western segment of the corridor straddling the Alaska Highway through the Big Delta and Mt. Hayes quadrangles. Deposits were mapped by interpretation of false-color infrared 1:65,000-scale aerial photographs taken in July 1978, August 1980, and August 1981 and verified by field checking in 2006 and 2007.

UNCONSOLIDATED DEPOSITS[1]

ALLUVIAL DEPOSITS

Oa — UNDIFFERENTIATED FLOODPLAIN ALLUVIUM—Chiefly well-sorted and well-stratified polymictic pebble gravel, sand, and silt comprising channel and overbank deposits of generally small streams; unfrozen to discontinuously frozen with low to moderate ice contents

Oaa — ACTIVE-FLOODPLAIN ALLUVIUM—Chiefly well-sorted and well-stratified layers and lenses of polymictic pebble gravel, sand, and silt with rare to scattered cobbles comprising river bars subject to recurrent inundation by streams every 5 yr or less (Chapin and others, 2006); mapped extent is a function of river level (stage) and reflects the transitory extent of exposed river bars at the time the photographs were taken; in braided and anastomosing reaches, active channels typically shift positions from year to year and present channel locations may differ from locations on the August 1980 photography on which the deposits were mapped; active alluvium underlies upper stream bank and active stream channels and includes point-bar and meander-scroll deposits (Brakenridge, 1988); composed dominantly of gravel and sand where stream is braided and anastomosing (Emmett and others, 1978; Burrows and others, 1979; Burrows and Harrold, 1983) and sand and silt bars and cover deposits where meandering; prone to earthquake-induced liquefaction where fine grained and unfrozen; where braided, subject to formation of extensive, thick seasonal-stream icings (aufeis); generally unfrozen, except seasonally frozen to depth of frost penetration; shallow water table

Oai — INACTIVE-FLOODPLAIN ALLUVIUM—Chiefly 2 to 20 ft (0.6 to 6 m) of overbank silty sand and sandy silt overlying gravelly, polymictic riverbed sand and sandy gravel beneath surfaces subject to flooding at least once or twice every century (Mason and Begét, 1991; Chapin and others, 2006); may include more than one terrace level; overbank sequences include flood-related features, like natural levees and crevasse splays near channels, and fine-grained back-levee swale deposits farther from channels (Brakenridge, 1988; Mann and others, 1995); surface pearl generally absent; generally unfrozen in younger areas and discontinuously frozen in older areas with low to moderate ice contents; active channels may be floored by 5 to 20 ft (1.5 to 6 m) of generally unfrozen sand and silty sand; fills of inactive channels may include 7 to 12 ft (2.1 to 3.7 m) of discontinuously frozen organic sand and silt with moderate to high ice contents over sand and gravelly sand

Oaw — ABANDONED-FLOODPLAIN ALLUVIUM—Chiefly 10 to 20 ft (3 to 6 m) of overbank sandy silt and silty sand overlying sandy, polymictic riverbed gravel beneath surfaces with widespread cover of lowland loess and local sand dunes and subject to inundation by streams once every 500 to 1,000 yr (Mann and others, 1995); may include several terrace levels; overbank sequences include flood-related features, like natural levees and crevasse splays near channels and fine-grained, peaty back-levee swale deposits farther from channels (Brakenridge, 1988; Mann and others, 1995); may contain organic-silt channel fills 7 to 20 ft (2.1 to 6 m) thick; surface pearl generally discontinuous to widespread in backwater areas away from channels; generally frozen with low to moderate ice contents

Oaf — ALLUVIAL-FAN DEPOSITS—Fan-shaped deposits of nonsorted to well-sorted gravel, sand, and silt with numerous cobbles and boulders in proximal zone; lithologies reflect bedrock of source area; in general, size of clasts decreases and degree of sorting increases downfan; typically mixed with debris-flow deposits in proximal part of fans; unfrozen to discontinuously frozen, except in fine-grained distal deposits where permafrost may be shallow and continuous; ice contents low to moderate

Oat — STREAM-TERRACE ALLUVIUM—Chiefly 4 to >20 ft (1.2 to >6 m) of organic sandy silt and silty sand overlying well-sorted, polymictic sand and gravel beneath stream terrace treads no longer subject to inundations by the stream that deposited the alluvium (Reger and Reger, 1982); may include several levels and incorporate outwash alluvium of Donnelly age in highest terraces; locally covered by ≥15 ft (≥4.5 m) of lowland loess and eolian-sand blanket and dunes complexes, particularly close to active sediment sources; other surface features, like expansion fans and bars, crevasse splays, and pebbly sand waves and dunes, relate to deposition and erosion during jökulhlaups of probable Delta and Donnelly ages; includes granitic flood-boulder fields emplaced on pebble-cobble gravel surfaces ≤8 ft (≤2.4 m) deep; sand matrix color varies from pale brown (10YR6/3) to brown (10YR5/3); 5 to 10 percent of foliated tillstones are typically split into plates by frost action and granitic tillstones are fresh to slightly weathered in weathered profiles, except locally, where foliated tillstones are shattered to small, platy fragments and granitic clasts are reduced to crumbly remnants by the growth of calcite (caliche) in the upper 3–4 ft (0.9–1.2 m) of the outwash deposit; silt caps 0.08 to 0.12 m (2 to 3 mm) and discontinuous; cover sands discontinuous and up to ~10 ft (~3 m) thick; average loess cover ~0.4 ft (~12 cm) thick and generally weathered light yellowish brown (10YR6/4) to brown (10YR5/3), except red (2.5YR5/6) where strongly oxidized after repeated wildfires (Peg and others, 2006); synthetic exhibit slight to moderate surface polish and pitting but no facets or keels in lags developed beneath loess covers; ice-wedge casts generally rare, but locally common and ≤5 ft (≤0.9 m) wide (Péwé and Reger, 1983a, p. 62-66); deformed wedge fillings composed of brown to greenish-gray silt with trace to some pebble gravel and scattered cobbles; unfrozen to discontinuously frozen with low ice contents

DELTA GLACIATION

Odgs — ESKER-KAME COMPLEX OF DELTA GLACIATION—Complex mixture of sand, pebble gravel with some sand and silt, and diamicton deposited in holes, tunnels, and narrow ice-walled valleys in stagnant glacial ice by sediment-charged meltwater streams and by debris flows generated by melting glacial ice; subangular to rounded cobbles and boulders range from rare to numerous; well to poorly sorted; thin to massive bedded; locally crossbedded; surface has high relief and is characterized by discontinuous, sinuous, anastomosing and bifurcating, steep-sided ridges (eskers) typically associated with small, steep-sided hills (kames); unfrozen

Odpv — OUTWASH OF DONNELLY GLACIATION—Massive to well-sorted, polymictic pebble gravel with some sand and scattered to numerous subrounded to subangular cobbles and boulders ≤7 ft (≤2.1 m) in diameter in proximal zones; surface weathering profiles ≤3 ft (≤0.9 m) deep; sand matrix color varies from pale brown (10YR6/3) to brown (10YR5/3); 5 to 10 percent of foliated tillstones are typically split into plates by frost action and granitic tillstones are fresh to slightly weathered in weathered profiles, except locally, where foliated tillstones are shattered to small, platy fragments and granitic clasts are reduced to crumbly remnants by the growth of calcite (caliche) in the upper 3–4 ft (0.9–1.2 m) of the outwash deposit; silt caps 0.08 to 0.12 m (2 to 3 mm) and discontinuous; cover sands discontinuous and up to ~10 ft (~3 m) thick; average loess cover ~0.4 ft (~12 cm) thick and generally weathered light yellowish brown (10YR6/4) to brown (10YR5/3), except red (2.5YR5/6) where strongly oxidized after repeated wildfires (Peg and others, 2006); synthetic exhibit slight to moderate surface polish and pitting but no facets or keels in lags developed beneath loess covers; ice-wedge casts generally rare, but locally common and ≤5 ft (≤0.9 m) wide (Péwé and Reger, 1983a, p. 62-66); deformed wedge fillings composed of brown to greenish-gray silt with trace to some pebble gravel and scattered cobbles; unfrozen to discontinuously frozen with low ice contents

DELTA GLACIATION

Odpfs — OUTWASH OF DELTA GLACIATION— Massive to well-sorted, polymictic pebble gravel with some sand and numerous subrounded to subangular cobbles and boulders ≤5.5 ft (≤1.7 m) in diameter; coarser in proximal zones and finer where distal; surface weathering profiles ≥12 ft (≥3.6 m) deep; sand matrix color varies from pale brown (10YR6/3) to very pale brown (10YR7/4); <50 percent of foliated and granitic clasts in weathered profile are rotten, silt caps on clasts in weathered profile ≥0.08 in (≥2 mm) thick; cover sands discontinuous and up to ~10 ft (~3 m) thick; loess cover typically 1 to 2 ft (0.3 to 0.6 m) thick, well-formed faceted and keeled ventifacts common in surface lags beneath loess covers; quartz pebbles in lags stained yellowish brown (10YR5/4) to very pale brown (10YR7/4); ice-wedge casts scattered to numerous and ≤5.5 ft (≤1.7 m) wide; deformed wedge fillings are typically eolian sand with trace to some silt and pebble gravel and may include scattered pebble ventifacts; unfrozen to discontinuously frozen with low ice contents

LACUSTRINE DEPOSITS

Ola — LAKE-BOTTOM DEPOSITS—Chiefly silt and clay with some sand and organic material deposited in ephemeral lakes in backwater areas of inactive floodplains and behind ice-shoved ramparts in large lakes; discontinuously to continuously frozen with moderate to high ice contents

Old — DELTA DEPOSITS—Chiefly sand and silt with some organic material deposited in a lake basin by a stream entering the lake; during floods of the Tanana River, streams normally draining the lake into the river reverse directions and carry floodwaters and sediments into the lake basin; discontinuously frozen with moderate to high ice contents

Olp — DEPOSITS OF ICE-SHOVED RIDGES—Single or multiple 3- to 5-ft-high (0.9- to 1.5-m-high) ridges parallel to and 2 to 15 ft (0.6 to 4.5 m) above modern lake shoreline; composed of overturned and severely and complexly deformed deposits of adjacent lake bottom, including fine to coarse clastic lake-bottom sediments and peat with thin interlayered light gray tephra; built by shoreward transport of lake-bottom sediments by wind-driven, drifting lake ice (Péwé and Reger, 1983b, fig. 22A and B); unfrozen to discontinuously frozen with low to moderate ice contents

PALUDAL DEPOSITS

Op — SWAMP DEPOSIT—Primarily fibrous and locally woody, autochthonous peat with organic silt and sand deposited in lowland sites (Kreig and Reger, 1982); ≥8 ft (≥2.4 m) thick; discontinuously to continuously frozen with moderate to high ice contents

RESIDUAL DEPOSITS

Opb — BLOCK RUBBLE—Nests and blankets of angular to subangular blocks derived by frost wedging and jacking of underlying bedrock (autochthonous block fields) on high-level surfaces and bedrock slopes, or as lags left by winnowing of sandy matrix from gelifluction deposits or thin till by subterranean piping (allochthonous block fields); locally may be included in units of thinly covered bedrock (b) and in shallow strath terraces; sizes of blocks are function of joint spacing in local bedrock; associated microrelief features formed by frost action and mass movement include stone polygons, stone nets and circles, stone stripes, nonsorted circles and hummocks, and soil lobes and benches; frost jacking locally active; discontinuously frozen with low to moderate ice contents

[1] Estimated contents of sand and silt, based on field observations, are indicated by the terms 'trace' and 'some.' 'Trace' implies a general composition of 0 to 12 percent. 'Some' implies a general composition of 12 to 30 percent. Estimated compositions >30 percent are not recorded in the field. Terms used to describe the estimated percentages of cobbles and boulders are 'numerous,' 'scattered,' and 'rare.' 'Numerous' implies that drilling through the deposit would encounter two cobbles or boulders in an interval of 2 ft (0.6 m). 'scattered' implies that drilling would encounter two cobbles or boulders in an interval of 10 to 15 ft (3 to 4.5 m); 'rare' implies that drilling would encounter two cobbles or boulders in an interval of >15 ft (>4.5 m). These numbers are field estimates only, based on surface observations, and may vary widely.

BEDROCK

b — UNDIFFERENTIATED BEDROCK—Outcrops of igneous, metamorphic, and sedimentary rocks; linear and curvilinear shallow troughs and linear changes of surface vegetation indicate the presence of planar bedrock structures

b/ — THINLY COVERED BEDROCK—Subcrops with <3 ft (<0.9 m) of loess cover; bedrock structures visible through thin veneer of surficial debris

b+b' — Bedrock outcrops and thinly buried subcrops that cannot be mapped separately

MAP SYMBOLS

(All map symbols may not appear on this sheet)

PHOTOINTERPRETED CONTACT — Dashed where approximately located, dotted where inferred

? QUESTIONABLE IDENTIFICATION

PROMINENT ESCARPMENT DISCUSSED IN TEXT—Dashed where approximately located; scarp slopes down toward Tanana River

U D ACTIVE HIGH ANGLE FAULT — Dashed where approximately located, queried where uncertain. Arrows indicate apparent direction of relative movement. U, upthrown block; D, downthrown block (Carver and others, 2008)

ACTIVE THRUST FAULT — Dashed where approximately located, dotted where inferred, queried where uncertain barbs on upper plate (Carver and others, 2008)

RC-1 LOCATION OF RADIOCARBON SAMPLE DISCUSSED IN TEXT

SP-1 LOCATION OF SOIL PIT DISCUSSED IN TEXT

REFERENCES CITED

Birch, C.J., 1976, Centerline and material site investigations, Alaska Highway alignment MP 1378 to 1376.5, Project No. HHS, 062-2(11): Alaska Department of Transportation and Public Facilities Engineering Geology and Soils report, 26 p.

Brakenridge, G.R., 1988, River flood regime and floodplain stratigraphy, in Baker, V.R., Kochel, R.C., and Patton, P.C., eds., Flood geomorphology: New York, John Wiley & Sons, p. 139–156.

Burrows, R.L., and Harrold, P.L., 1983, Sediment transport in the Tanana River near Fairbanks, Alaska, 1980–81: U.S. Geological Survey Water-Resources Investigations Report 83-4064, 116 p.

Burrows, R.L., Parks, Bruce, and Emmett, W.W., 1979, Sediment transport in the Tanana River in the vicinity of Fairbanks, Alaska, 1977–78: U.S. Geological Survey Open File Report 79-1539, 37 p.

Carter, L.D., and Galloway, J.P., 1978, Preliminary engineering geologic maps of the proposed natural gas pipeline route in the Tanana River valley, Alaska: U.S. Geological Survey Open File Report 78-794, 26 p., 3 map sheets, scale 1:125,000.

Carver, G.A., Bemis, S.P., Solie, D.N., and Obermiller, K.E., 2008, Active and potentially active faults in or near the Alaska Highway corridor, Delta Junction to Dot Lake, Alaska: Alaska Division of Geological & Geophysical Surveys Preliminary Interpretive Report 2008-3d, 32 p.

Chapin, F.S., III, Viereck, L.A., Adams, P.C., Van Cleve, Keith, Fastie, C.L., Ott, R.A., Mann, Daniel, and Johnson, J.F., 2006, Successional processes in the Alaskan boreal forest, in Chapin, F.S., III, Oswood, M.W., Van Cleve, Keith, Viereck, L.A., and Verbyla, D.L., eds., Alaska's changing boreal forest: New York, Oxford University Press, p. 100–120.

Costa, J.E., 1988, Rheologic, geomorphic, and sedimentologic differentiation of water floods, hyperconcentrated flows, and debris flows, in Baker, V.R., Kochel, R.C., and Patton, P.C., eds., Flood geomorphology: New York, John Wiley & Sons, p. 113–122.

Duk-Rodkin, Alejandra, Barendregt, R.W., Froese, D.G., Weber, Florence, Enkin, Randy, Smith, I.R., Zazula, G.D., Waters, Pamela, and Klassen, Rudy, 2004, Timing and extent of Plio-Pleistocene glaciations in north-western Canada and east-central Alaska, in Ehlers, J., and Gibbard, P.L., eds., Quaternary glaciations—extent and chronology, part II: North America: New York, Elsevier, Developments in Quaternary Sciences, v. 2, p. 313–345.

Emmett, W.W., Burrows, R.L, and Parks, Bruce, 1978, Sediment transport in the Tanana River in the vicinity of Fairbanks, Alaska, 1977: U.S. Geological Survey Open File Report 78-290, 28 p.

Holmes, G.W., 1965, Geologic reconnaissance along the Alaska Highway, Delta River to Tok Junction, Alaska: U.S. Geological Survey Bulletin 1141-H, 19 p., 1 map sheet, scale 1:125,000.

Kreig, R.A., and Reger, R.D., 1982, Air-photo analysis and summary of landform soil properties along the route of the Trans-Alaska Pipeline System: Alaska Division of Geological & Geophysical Surveys Geologic Report 66, 148 p.

Lindholm, G.F., Thomas, L.A., Davidson, D.T., Handy, R.L., and Roy, C.J., 1959, Soils near Big Delta and Fairbanks, *in* Davidson, D.T., and Roy, C.J., eds., The geology and engineering characteristics of some Alaskan silts: Iowa Engineering Experiment Station Bulletin 186, p. 33–70.

Mann, D.H., Fastie, C.L., Rowland, E.L., and Bigelow, N.H., 1995, Spruce succession, disturbance, and geomorphology on the Tanana River floodplain, Alaska: Ecoscience, v. 2, no. 2, p. 184–199.

Mason, O.K., and Begét, J.E., 1991, Late Holocene flood history of the Tanana River, Alaska, U.S.A.: Arctic and Alpine Research, v. 23, no. 4, p. 392–403.

Péwé, T.L., 1951, An observation of wind-blown silt: Journal of Geology, v. 59, p. 399–401.

———1955, Origin of the upland silt near Fairbanks, Alaska: Alaska Geological Society of America Bulletin, v. 66, no. 6, p. 699–724.

Péwé, T.L., and Holmes, G.W., 1964, Geology of the Mt. Hayes D-4 Quadrangle, Alaska: U.S. Geological Survey Miscellaneous Geologic Investigations Map I-394, scale 1:63,360, 2 map sheets.

Péwé, T.L., and Reger, R.D., 1983a, Delta River area, Alaska Range, *in* Péwé, T.L., and Reger, R.D., eds., Guidebook to permafrost and Quaternary geology along the Richardson and Glenn highways between Fairbanks and Anchorage, Alaska: Alaska Division of Geological & Geophysical Surveys Guidebook 1, p. 47–135.

———1983b, Middle Tanana River valley, *in* Péwé, T.L., and Reger, R.D., eds., Guidebook to permafrost and Quaternary geology along the Richardson and Glenn highways between Fairbanks and Anchorage, Alaska: Alaska Division of Geological & Geophysical Surveys Guidebook 1, p. 5–45.

Ping, C.L., Boone, R.D., Clark, M.H., Packer, E.C., and Swanson, D.K., 2006, State factor control of soil formation in interior Alaska, in Chapin, F.S., III, Oswood, M.W., Van Cleve, Keith, Viereck, L.A., and Verbyla, D.L., eds., Alaska's changing boreal forest: New York, Oxford University Press, p. 21–38.

Schoephorster, D.B., 1973, Soil survey of Salcha–Big Delta areas, Alaska: U.S. Department of Agriculture Soil Conservation Service, 51 p., scale 1:31,680, 26 map sheets.

Sloan, C.E., Zenone, Chester, and Mayo, L.R., 1976, Icings along the trans-Alaska pipeline route: U.S. Geological Survey Professional Paper 979, 31 p.

Springer, W.J., George, T.H., and Brell, R.M., 1976, Identification of flood hazard resulting from aufeis formation in an interior Alaskan stream: Unpublished University of Alaska Geophysical Institute report for U.S. Department of Agriculture Soil Conservation Service, 12 p.

Weber, F.R., 1986, Glacial geology of the Yukon-Tanana Upland, in Hamilton, T.D., Reed, K.M., and Thorson, R.M., eds., Glaciation in Alaska: The geologic record: Anchorage, Alaska Geological Society, p.79–98.

Multifaceted greenstone ventifact on early Delta terminal moraine adjacent to proximal outwash fan that provided the cutting sand. (Photograph taken by R.D. Reger, 9/12/06.)

The State of Alaska makes no express or implied warranties (including warranties for merchantability and fitness) with respect to the character, functions, or capabilities of the electronic data or products or their appropriateness for any user's purposes. In no event will the State of Alaska be liable for any incidental, indirect, special, consequential, or other damages suffered by the user or any other person or entity whether from the use of the electronic services or products, or any failure thereof or otherwise. In no event will the State of Alaska's liability to the Requestor or anyone else exceed the fee paid for the electronic service or product.

DGGS publications can be purchased or ordered from the Fairbanks office at:
Alaska Division of Geological & Geophysical Surveys
3354 College Road
Fairbanks, AK 99709-3707
451-5000 (phone) dggspubs@alaska.gov
451-5050 (fax) http://www.dggs.dnr.state.ak.us

State of Alaska
Department of Natural Resources
Division of Geological & Geophysical Surveys